

# Notice of Violation

**Date: July 16, 2007**

**Address: 123 Kaboom St., Anytown, TX 77777**

**(Single Family Residence)**

**Owner: John Doe**

**Phone: (555) 555-5555**

**Contractor: XYZ Electric – Joe Electrician Phone: (555) 555-5556**

**Violation: On this date, while performing an electrical inspection of an electrical feeder to an outbuilding on the property, I noticed the following:**

The electrical service has been altered by an electrical contractor, and many electrical hazards were found —

- 1. Overfused conductors – NEC 240.4, 310.15(B)(6) – 200-ampere service panel is installed with 100-ampere conductors**
- 2. No grounding of service – NEC 250.4(A) & (B), 250.52, 250.66**
- 3. Exposed live parts – NEC 110.27**
- 4. Wrong equipment for use – NEC 110.3(B) an indoor type load-center has been installed outdoors in a wet location**
- 5. Electrical service panel newly installed has damaged, cut, and bent busbar – NEC 110.12(C )**
- 6. Overhead service conductor clearances are too low – NEC 230.24**
- 7. No main bonding jumper installed in service panel – NEC 250.28**
- 8. Electrical service is undersized for the load and this size of structure – per NEC 220 – electrical load calculation is required.**
- 9. Electrical service was placed in a location not acceptable to electrical utility standards. The electric utility was not contacted prior to the installation, as required by utility standards, and City Ordinance # 80.10**
- 10. No electrical permit was secured for the electrical service replacement work. Violation City Ordinance # 80.10**
- 11. An electrical permit fee is required to be paid at City Hall before repair work may be commenced. Provide electrical load calculation to this office at the time the permit is purchased.**
- 12. All electrical service violations listed above must be corrected with 15 days—and called for re-inspection by this office—on or before the end of the workday on July 31, 2007. Failure to comply with this notice of violation will result in the electrical power to this address being disconnected by the electric utility on July 31, 2007.**
- 13. The electrical connection of the feeder to the outbuilding must be ready for inspection at the time of service inspection. The remainder for the feeder inspection, which was permitted, is approved for ditch and rough-in (wall/ceiling cover) inspection this date, July 16, 2007.**
- 14. Owner and electrical contractor have both received a copy of this violation notice on this date, July 16, 2007, as signed below.**
- 15. Electrical contractor must be licensed per state law 19.28 RCW.**
- 16. If any questions, contact: I. Keepu Safe, Electrical Inspector, @ (555) 555-5557.**

Figure 1. Notice of Violation [sample only]